SECURIKEY®

Possible Secu A and B installation issues





SECURIKEY®

Possible Secu A and B installation issues





This is where it gets trapped if your not careful, In-between case and dial ring. Then the turning motion acts like a scissor action over time.

Rotate to ensure free movement and nothing is trapped

All locks have some areas of possible problem.
The 2 areas with the Secu locks are ;

1. **If the location screws are not used for the dial ring the sticky pads (now reduced in size and only for location purposes) work loose and cause the dial to wobble and shear the cable at this point.**
2. **The cable becomes trapped in between the dial ring and key pad , the screw is tightened in the spindle and this crushes the cable causing long term cable sheer or intermittent faults. Only evident during pro-longed use**



Locktite the back 2 screws because if they work loose the cam inside cannot Passover the top and causes lockout by blocking bolt retraction